


Flow Chart



Torque table		
Gear II bar	Nm max	ft.lbs max
2	385	283
3	485	358
4	615	453
5	750	555
6	920	680
7	1130	833

Gear I bar	Nm max	ft.lbs max
2	1225	902
3	1545	1141
4	1955	1443
5	2395	1768
6	2935	2165
7	3595	2652

Operating pressure on the machine
Air Consumption:
 21 - 32 cfm.

Torque

All curves are approximate values. Unstable compressed air values can cause deviations.

TECHNICAL DATA

AIR-Tite

AT 2650F-2

Model

16-4-

Equipment Serial Number

Date of Delivery



TITAN
 TECHNOLOGIES INTERNATIONAL, INC.

SUPERIOR BOLTING SOLUTIONS

www.TitanTi.com