


Flow Chart



bar	Nm max	ft.lbs max
2	1490	1099
3	1885	1391
4	2385	1759
5	2920	2154
6	3575	2638
7	4380	3231

Operating pressure on the machine
Air Consumption:
 21 - 32 cfm.

Torque

All curves are approximate values. Unstable compressed air values can cause deviations.

TECHNICAL DATA

AIR-Tite

AT 3200R

Model

18-92-

Equipment Serial Number

Date of Delivery



TITAN
 TECHNOLOGIES INTERNATIONAL, INC.

SUPERIOR BOLTING SOLUTIONS

www.TitanTi.com