


Flow Chart



Torque table		
Gear II bar	Nm max	ft.lbs max
2	4725	3485
3	5975	4408
4	7560	5576
5	9260	6829
6	11340	8364
7	13890	10244

Gear I bar	Nm max	ft.lbs max
2	16540	12198
3	20920	15429
4	26460	19517
5	32405	23903
6	39690	29275
7	48610	35855

Operating pressure on the machine
Air Consumption:
 21 - 32 cfm.

Torque

All curves are approximate values. Unstable compressed air values can cause deviations.

TECHNICAL DATA

AIR-Tite

AT 35000F-2

Model

454-5-

Equipment Serial Number

Date of Delivery

